

MIT/IL SOFTWARE ANOMALY REPORT

MSC REPORT NO. L-1B-02
PROGRAM LUMINARY
PROGRAM REVISION 116

1.1 ORIGINATOR: P. VOLANTE	1.2 ORGANIZATION: MIT/IL	1.3 DATE: 8/20/69	1.4 ORIGINATOR CONTROL NO.
1.5 DESCRIPTION OF ANOMALY: R29 will not achieve RR lockon. <div style="text-align: right;">CONTINUED ON PAGE</div>			
1.6 DESCRIPTION OF RUN: Nominal ascent. <div style="text-align: right;">CONTINUED ON PAGE</div>			
- MIT ANALYSIS -			
2.1 CAUSE: Incorrect computation of shaft commands by R29. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.2 RECOGNITION: None. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.3 MISSION EFFECT: R29 cannot be used. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.4 AVOIDANCE PROCEDURE: Bypass R29 by having the RR mode switch not in the LGC position during ascent. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.5 RECOVERY PROCEDURE: None. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.6 PROGRAM CORRECTION: Fix coding. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc): Work-around for LUMINARY 1B; fix in LUMINARY 1C. <div style="text-align: right;">CONTINUED ON PAGE</div>			
2.8 RECOMMENDED RE-TESTING: Ascent with R29. <div style="text-align: right;">CONTINUED ON PAGE</div>			
3.1 NASA DIRECTION: <div style="text-align: right;">CONTINUED ON PAGE</div>		2.9 MIT/IL SIGNATURE: <i>Russell McLaughlin</i>	2.10 DATE: <i>22 Aug 69</i>
		4.1 CLOSING ACTION TAKEN: <div style="text-align: right;">CONTINUED ON PAGE</div>	
3.2 NASA/MSC SIGNATURE:	3.3 ORGANIZATION	3.4 DATE:	4.2 SIGNATURE:
			4.3 ORGANIZATION:
			4.4 DATE: