

# MIT/IL SOFTWARE ANOMALY REPORT

MIT REPORT NO.	LNY 88
PROGRAM	LUMINARY
PROGRAM REVISION	99

1.1 ORIGINATOR: R. COVELLI	1.2 ORGANIZATION: MIT/IL	1.3 DATE: 7/10/69	1.4 ORIGINATOR CONTROL NO.
-------------------------------	-----------------------------	----------------------	----------------------------

1.5 DESCRIPTION OF ANOMALY:

A hardware restart while R12 is repositioning the landing radar antenna will prevent the antenna from achieving position 2, and will cause 511 alarms every 2 seconds in P64. A software restart in the same interval will not prevent the antenna from achieving position 2, but use of the radar will be inhibited.

CONTINUED ON PAGE

1.6 DESCRIPTION OF RUN:

Restart testing at Grumman.

CONTINUED ON PAGE

- MIT ANALYSIS -

2.1 CAUSE:

Landing radar repositioning routine is not restart protected.

CONTINUED ON PAGE

2.2 RECOGNITION: If hardware restart shortly after P64, 511 alarms will appear. If caused by software restart, the only recognition is that NOLRREAD flag is set, even though antenna is in position 2.

CONTINUED ON PAGE

2.3 MISSION EFFECT:

Landing radar data will not be used from P64 on.

CONTINUED ON PAGE

2.4 AVOIDANCE PROCEDURE:

None.

CONTINUED ON PAGE

2.5 RECOVERY PROCEDURE:

Move LR position switch to hover, then set RPCRTIME to POSMAX and reset NOLRREAD flag and PSTHIGAT flag!...

CONTINUED ON PAGE 2

2.6 PROGRAM CORRECTION:

Set up restart group for HIGATJOB.

CONTINUED ON PAGE

2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc):

Fix in LUMINARY 1B.

CONTINUED ON PAGE

2.8 RECOMMENDED RE-TESTING:

Restart run.

CONTINUED ON PAGE

2.9 MIT/IL SIGNATURE: <i>George W. Cherron</i>	2.10 DATE: 7-15-69
---	-----------------------

3.1 NASA DIRECTION:	4.1 CLOSING ACTION TAKEN: /
CONTINUED ON PAGE	CONTINUED ON PAGE

3.2 NASA/MSC SIGNATURE:	3.3 ORGANIZATION	3.4 DATE:	4.2 SIGNATURE:	4.3 ORGANIZATION:	4.4 DATE:
-------------------------	------------------	-----------	----------------	-------------------	-----------

# MIT/IL SOFTWARE ANOMALY REPORT

1.1 ORIGINATOR: R. COVELLI	1.2 ORGANIZATION: MIT/IL	1.3 DATE: 7/10/69	1.4 ORIGINATOR CONTROL NO.	MSC REPORT NO. LNY 88
				PROGRAM LUMINARY
				PROGRAM REVISION 99

## 2.5 Recovery Procedure:

V21N1E 3427E 37777E

V25N7E 107E 3000E OE