

MIT/IL SOFTWARE ANOMALY REPORT

MIT REPORT NO. LNY 90
PROGRAM Luminary
PROGRAM REVISION 99

1.1 ORIGINATOR: R. Covelli/P. Weissman	1.2 ORGANIZATION: MIT/IL	1.3 DATE: 7/15/69	1.4 ORIGINATOR CONTROL NO.
---	-----------------------------	----------------------	----------------------------

1.5 DESCRIPTION OF ANOMALY: If an engine fail occurs in P63 between TIG and throttle up, the flashing V97N63 display will be overwritten by the static V06N63 display. The V97 display comes up once per second, while the V06 display comes up once per two seconds; so that a response to the V97 display can be lost.

CONTINUED ON PAGE

1.6 DESCRIPTION OF RUN:
Inspect coding

CONTINUED ON PAGE

- MIT ANALYSIS -

2.1 CAUSE:
Coding error

CONTINUED ON PAGE

2.2 RECOGNITION:
V97N63 and V06N63 displays replacing one another. A response to the flashing V97 may be ignored.

CONTINUED ON PAGE

2.3 MISSION EFFECT:
Longer time required to respond to V97 in P63

CONTINUED ON PAGE

2.4 AVOIDANCE PROCEDURE:
None

CONTINUED ON PAGE

2.5 RECOVERY PROCEDURE:
Respond to V97 again, as often as necessary.

CONTINUED ON PAGE

2.6 PROGRAM CORRECTION:
Fix code.

CONTINUED ON PAGE

2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc):
Fix in LUM 1 B

CONTINUED ON PAGE

2.8 RECOMMENDED RE-TESTING:
Engine fail in P63

CONTINUED ON PAGE

2.9 MIT/IL SIGNATURE: <i>George W. Cherry</i>	2.10 DATE: 8/5/69
--	----------------------

3.1 NASA DIRECTION:

CONTINUED ON PAGE

4.1 CLOSING ACTION TAKEN:

CONTINUED ON PAGE

3.2 NASA/MSC SIGNATURE:	3.3 ORGANIZATION	3.4 DATE:	4.2 SIGNATURE:	4.3 ORGANIZATION:	4.4 DATE:
-------------------------	------------------	-----------	----------------	-------------------	-----------