

Massachusetts Institute of Technology
Instrumentation Laboratory
Cambridge, Massachusetts

LUMINARY Memo #123

To: Distribution
From: D. Eyles
Date: 18 November 1969
Subject: More About Delta-Guidance

Delta-guidance is running in AMELIA 11 (as also in some of the earlier revisions). which in other respects is just like LUMINARY 130, which was just released as 1C.

Here are the patches required:

<u>location</u>	<u>old</u>	<u>new</u>	<u>symbolic</u>	<u>new</u>
05, 2310	bad word	03641	ECADR	TTT/8
31, 2213	62325	63770	BZMF	31, 3770
31, 3770	unused	34755	CA	ZERO
31, 3771	unused	55610	TS	FWEIGHT
31, 3772	unused	55611	TS	FWEIGHT +1
31, 3773	unused	12325	TCF	THDUMP

On the next page is given the initialization which is different from that for LUMINARY 130. See Luminary Memo #115 for a description of the new parameters. Note that DELTTTAP has been eliminated since the initial TGO for P64 equals P63's final TGO. The values given are Allan Klumpp's latest. The only number not given is RPCRTIME which should be set equal to TENDBRAK to make the LR antenna reposition at high-gate.

TRAJECTORY DESIGN DEPENDENT DATA

VIGN	2D +1.69099951	E+ 18-10	VIGG	+1.69099951	E+ 3	002471	00416	21726
RIGNX	2D -4.02612533	E+ 4B-24	RIGXG	-4.02612533	E+ 4	002473	77730	65653
RIGNZ	2D -4.36270484	E+ 5B-24	RIGZG	-4.36270484	E+ 5	002475	77125	76427
KIGNX/B4	2D -.038601937		KX	+6.17630999	E-	002477	76607	61356
KIGNY/B8	2DEC 0					002501	00000	00000
KIGNV/B4	2D -.156402587		KV	+4.10000000	E+ 2	002503	72775	57777
RBRIGX	2D +3.79762136	E+ 2B-24		+3.79762136	E+ 2	002402	00000	13674
RAPIGX	2D +2.93043502	E+ 1B-24		+2.93043502	E+ 1	002404	00000	00725
RBRIGZ	2D -4.52071878	E+ 4B-24		-4.52071878	E+ 4	002406	77723	73214
RAPIGZ	2D -9.39081728	E+ 0B-24		-9.39081728	E+ 0	002410	77777	77551
VBRIGX	2D +5.46925427	E- 1B-7		+5.46925427	E+ 1	002412	00106	00152
VAPIGX	2D +9.50627990	E- 3B-7		+9.50627990	E- 1	002414	00001	06740
VBRIGZ	2D -6.27549803	E+ 0B-7		-6.27549803	E+ 2	002416	76334	67436
VAPIGZ	2D -5.51227250	E- 3B-7		-5.51227250	E- 1	002420	77777	51327
ABRTGX	2D +5.87004660	E- 2		+1.14649347	E+ 0	002422	01701	27746
AAPIGX	2D +6.14681267	E- 3		+1.20054934	E- 1	002424	00144	26546
ABRTGZ	2D -2.62579450	E- 1		-5.12850488	E+ 0	002426	67461	74575
AAPTGX	2D -3.34411788	E- 4		-6.53148024	E- 3	002430	77772	60527
JBRIGX	2D +1.38353801	E- 1		+6.18489691	E- 3	002432	04332	31172
JAPIGX	2D +7.66667726	E- 2		+3.42727181	E- 3	002434	02350	03360
JBRIGZ	2D -9.74846498	E- 2		-4.35790344	E- 3	002436	74702	71757
JAPIGZ	2D +2.61468828	E- 1		+1.16885674	E- 2	002440	10273	34760
SBRIGX	2D +1.38918454	E- 2		+1.89518398	E- 6	002442	00343	23250
SAPIGX	2D +8.21245308	E- 1		+1.12037738	E- 4	002444	32217	11037
SBRIGZ	2D +7.59909552	E- 3		+1.03670056	E- 6	002446	00174	20073
SAPIGZ	2D +1.45871904	E- 1		+1.99004586	E- 5	002450	04525	36707
BBR	1D -8.88576611	E+ 0B-8				002452	76706	
CRR	1D +3.94784176	E+ 1B-8				002453	04737	
RAP	1D -8.88576611	E+ 0B-8				002454	76706	
CAP	1D +3.94784176	E+ 1B-8				002455	04737	
VCOEBK	1D +3.05926514	E+ 1B-8				002456	03646	
ACOEBR	1D +2.37069853	E+ 1B-8				002457	02755	
VCOEAP	1D +3.05926514	E+ 1B-8				002460	03646	
ACOEAP	1D +2.37068853	E+ 1B-8				002461	02755	
JCOEBR	1D +1.38211192	E+ 1B-8				002462	02265	
SCOEBR	1D +1.59353531	E+ 1B-8				002463	01774	
JCOEAP	1D +1.38211192	E+ 1B-8				002464	02265	
SCOEAP	1D +1.59353531	E+ 1B-8				002465	01774	
ECDOWN	DEC 2236					002466	04274	
UPCRIT	1D +0.00000000	E+ 0B-10	UPCRIT	+0.00000000	E+ 0	002467	00000	
DOWNCRIT	1D -3.04799999	E- 2B- 7	DOWNCRIT	-3.04799999	E+ 0	002470	77773	
TENDBRBK	1D +1.62000000	E+ 4B-17	TENDBRBK	+1.62000000	E+ 2	003423	03751	
TENDAPPR	1D +2.00000000	E+ 3B-17	TENDAPPR	+2.00000000	E+ 1	003424	00423	
LOWCRIT	1D + 2272		FLO	+2.84908594	E+ 4	003426	04340	
HIGHCRIT	1D + 2347		FHI	+2.94249859	E+ 4	003425	04453	

Runs on AMELIA have disclosed several interesting facts:

(1) Forward redesignations of the landing site, for instance a 10000 foot downrange noun 69 input at the start of P64, can cause pulse-outs, as well as cause the LM to pitch forward from the vertical. Large backward redesignations also cause pulse outs, but this is not unexpected.

(2) A lateral velocity noise spike at TGO = -50 in P64 of 1.5 f/s after incorporation causes oscillations in roll. This is the problem cured for LUMINARY 1A by adding coefficients containing LEADTIME to the guidance equation (see Luminary Memo # 97). Maybe crafty choosing of A and B will clear this up, averting the necessity of putting back LEADTIME, which would be hard.

(3) It is confirmed that large downrange redesignations in P63 (via noun 69) cost no fuel - 50000 feet at the start of the burn was tried and actually less propellant was used.

Some plots are appended: first and second the thrust and pitch profiles of the nominal run for the interesting ways they differ from the old style, and third the roll (strictly CDUZ) in response to the lateral velocity noise spike.

CDUZ AND CDUZD

DELTA-GUIDANCE (AMELIA 11) VELOCITY NOISE SPIKE AT TGO -50 IN P64

-10

-5

0


-5

-10

-15

-20

DEGREES



↑ 100FT THRU P64

↑ P64 THRU 500FT

↑ 1000FT

↑ 500FT

↑ P65

↑ ENG OFF TDOWN

397850

397900

397950

398000

398050

SECONDS G.E.T.