

APOLLO -14

J. LAWRENCE

# APOLLO 14 MISSION H-1

## EQUIPMENT

GN 214 (CM-110)

GN 611 (LM-8)

## MISSION

MANNED LUNAR LANDING IN FRA Mauro HIGHLANDS (17°W x 3°S.)

## LAUNCH

31 JANUARY 1971, 3:23 PM EST  $\approx$  4 HR WINDOW, SAIV<sup>#</sup> 50

## MISSION OBJECTIVES

LUNAR SURFACE EVA (2 PERIODS UP TO 5 HOURS)

CONTINGENCY SAMPLE COLLECTION

PORTABLE LIFE SUPPORT SYSTEMS RECHARGE

PRE-PDI LM STATE VECTOR UPDATE EVALUATION

BULK SAMPLE COLLECTION

PHOTOGRAPHS OF CANDIDATE EXPLORATION SITES

LUNAR SURFACE CHARACTERISTICS

LUNAR ENVIRONMENT VISIBILITY

LANDED LM LOCATION

PHOTOGRAPHIC COVERAGE

TELEVISION COVERAGE

APOLLO LUNAR SURFACE EXPERIMENTS, DEPLOYMENT / CONDUCT

## CREWS

	<u>PRIME CREW</u>	<u>BACK UP CREW</u>
COMMANDER	SHEPARD	CERNAN
CM PILOT	ROOSA	EVANS
LM PILOT	MITCHELL	ENGLE

# APOLLO 14

## OPEN G & N PROBLEMS

OWA DUST COVER MOUNTING HARDWARE MISSING

### FRR ITEMS REVIEWED AT MSC FRR BOARD

- 1) OWA DUST COVER MOUNTING HARDWARE MISSING
- 2) FLATPACK GOLD BALL BOND
- 3) FLATPACK "CBCS"
- 4) "A" HARNESS -13 SHORT CIRCUIT
- 5) FIVE WIRE TRANSFORMER

### APOLLO 13 CM 109-HARDWARE ANOMOLY

- 1) OWA "ZERO OPTICS DRIFT

### CM-GENERIC ITEMS

- 1) AN ADDED PREVENTIVE MAINTENANCE REQUIREMENT OF 2000 HOURS FOR IMU BLOWER MOTORS IS BEING APPLIED TO IMU'S RECYCLED FOR RETEST/REPAIR OR MODIFICATION. THE BLOWER MOTORS IN IMU 7 ARE WELL WITHIN THIS PREVENTIVE MAINTENANCE PERIOD, HAVING EXPERIENCED 211 HOURS (S/N 210) AND 211 HOURS (S/N 208) PRIOR TO TCP-K-000.
- 2) CML 45 HAS COMPLETED THE MODULE-LEVEL FLATPACK CONTAMINATION Y<sub>A</sub>-Y<sub>B</sub> VIBRATION

- ~~OF~~ OF 60 MINUTES AND COMPUTER LEVEL YA - YB VIBRATION OF 14 MINUTES. ECDU 29 HAS EXPERIENCED NO YA - YB VIBRATION SCREEN.
- 3) ALL DSKY RELAYS HAVE COMPLETED THE RELAY-LEVEL VIBRATION. THE DSKY RELAYS HAVE BEEN VIBRATED AT THE SYSTEM LEVEL FOR CONTAMINATION DETECTION.
  - 4) THE OVA-21 MOTOR TACHOMETERS IN APOLLO 14 WILL HAVE ACCRUED 4.2 YEARS OR LESS TOTAL TIME, INCLUDING MISSION TIME, WHICH IS CONSIDERED ACCEPTABLE FOR THIS MISSION.
  - 5) EL MODULES 185 AND 195 CURRENTLY IN CM 110 HAVE SUCCESSFULLY COMPLETED THE VACUUM SCREEN FOR SAFETY GLASS DELAMINATION.
  - 6) PINS BRUSH PLATED ON A-17, C-16, AND H-17 HARNESS. ALL THREE HARNESSES WERE LATER SUBJECTED TO THE IMPROVED CLEANING PROCESS.
  - 7) IMW-WIRE BREAKAGE - IMW-7 HAS A NEW 3D HARNESS.
  - 8) IMW QUICK DISCONNECTS ARE TO BE REPLACED AFTER 20 HOURS EXPOSURE TO

ISOPROPYL ALCOHOL. THE INSTALLED QUICK DISCONNECTS, P/N 1000135, S/N 30 AND S/N 419 HAVE HAD 5.9 HOURS EXPOSURE TO ISOPROPYL ALCOHOL.

## Problem Review

### Blower Motor Failure History

Blower S/N	IMU S/N	OPERATING TIME	DATE OF FAILURE REPORT
99	24	553	23 OCT 1967
91	7	1,760	4 MAR 1970
153	48	734	20 MAY 1970
46	9	1,616	16 JULY 1970
27	14	* 2,535 AND FLIGHT	
158	46	935 AND FLIGHT	28 AUGUST 1970

\* Blower S/N 27 WAS FOUND INOPERATIVE WHEN THE IM WAS TORN DOWN FOR PART EVALUATION AS PART OF THE ALLIS PROGRAM. (APOLLO 9)

### Blower Motor Mission History

FLIGHT	S/C	IMU S/N	Hours
APOLLO 7	CM-101	8	* 2,400 2,500
APOLLO 8	CM-103	23	2,200 2,200
APOLLO 9	CM-104	14	2,535 2,902
	LM-3	19	1,823 1,823
APOLLO 10	CM-106	45	721 721
	LM-4	27	1,333 1,333

Apollo 11	CM-107	17	1441	2,865
	LM-5	11	3,298	799
Apollo 12	CM-108	46	872	872
	LM-6	15	2,426	2,426
Apollo 13	CM-109	47	700	700
	LM-7	28	358	769

\* INCLUDING FLIGHT TIME, OTHER TIMES SHOWN ARE PRIOR TO FLIGHT.

Apollo 14 Blower OPERATING HOURS - 30 SEPT 70.

<u>S/C</u>	<u>IMU S/N</u>	<u>BLOWER</u>	<u>HOURS</u>
CM-110	7	210 200	211 211
LM-8	21	213 80	765 1,725

### ECDU - 20

#### PROBLEM:

A MASTER ALARM OCCURRED DURING ICDU ZERO SEQUENCE OF G&N FUNCTIONAL TEST IN CM-113 AT NAR. ICDU FAIL AND ISS WARNING WERE PRESENT. THE IGA CDU COARSE ERROR WAS OSCILLATING DUE TO THE IGA READ COUNTER DECREMENTING AT -70° SECOND. ECDU S/N 20 WAS REMOVED FROM G&N 216 AND SENT TO DELCO.

#### VERIFICATION:

ECDU WAS TESTED IN THE G&N CONFIGURATION IN AN ENGINEERING LABORATORY SYSTEM AND THE OSCILLATION WAS REPEATED. THE ECDU TRAYS WERE SEPARATED. THE INNER GIMBAL READ COUNTER 212 WAS SWAPPED WITH ANOTHER READ COUNTER. THE OSCILLATION

PROBLEM FOLLOWED READ COUNTER 212. THE FAILURE WAS ISOLATED TO THE  $2^{-12}$  BIT COUNTER STAGE.

### ISOLATION:

READ COUNTER P/N 2007140 S/N 212 WAS SENT RAYTHEON FOR FAILURE ISOLATION. THE FAILURE OF THE  $2^{-12}$  BIT COUNTER STAGE WAS VERIFIED AT RAYTHEON. FAILURE ANALYSIS HAS ISOLATED THE FAILURE TO A SHORT CIRCUIT BETWEEN LAYER No 1 AND No 15 IN THE MATRIX. (HIGH RESISTANCE SHORT)

"A" HARNESS  
P/N 2021406, S/N 13

### Problem

DURING POWER UP OF G&N 214 IN CM-110, OPTICS TURN ON CAUSED 5.25 VOLTS TO BE APPLIED TO THE IMU OPERATE BUSS. APPLICATION OF IMU OPERATE POWER CAUSED 8 VOLTS TO BE APPLIED TO THE OPTICS OPERATE BUSS.


### VERIFICATION

LABORATORY SIMULATION WAS ACCOMPLISHED BY SHORTING THE OUTPUTS OF THE 8002190033 AND 8002190155 MODULES. X-RAY INSPECTION REVEALED AN APPARENT WIRE STRAND BETWEEN PINS 40 AND 41 OF CONNECTOR 56P1 (8002190155/033 SIGNALS). CONTINUITY CHECKS CONFIRMED AN INTERMITTENT SHORT BETWEEN THESE TWO CIRCUITS.

## ISOLATION:

CONNECTOR WAS SECTIONED AND A METALLIC PIECE WAS VERIFIED AS CAUSE OF SHORT BETWEEN PINS 40 AND 41. OPTICAL MEASUREMENT VERIFIES APPROXIMATE 34 GAUGE SIZE OF FOREIGN MATERIAL (SAME AS USED IN WIRES ON PINS 40 AND 41). HOWEVER, ALL STRANDS WERE PRESENT AND INTACT AT CRIMP JOINTS ON WIRES TO PINS 40 AND 41. ANALYSIS OF FOREIGN MATERIAL TO DETERMINE METALLIC CONTENT IS IN PROGRESS.





- 9

COMPUTER S/N 51

PROBLEM:

DURING SPACECRAFT TESTING, OUTPUT CHANNEL 12 BIT 13 (SATURN INJECT SEQUENCE START) WAS SET AND COULD NOT BE RESET.


VERIFICATION:



ANALYSIS INDICATED A PROBLEM WITH THE A-16 LOGIC MODULE ONLY. THE A-16 MODULE WAS REMOVED FROM THE COMPUTER AT RAYTHEON AND TESTED AT THE MODULE LEVEL PINS 461 AND 462 REMAINED A HARD "1" WHILE EXERCISING THE CLEAR SIGNAL AT PIN 361.


ISOLATION:

GATE 27 WAS DEPOTTED AND THE HARD "1" CONDITION WAS VERIFIED AT THE ASSOCIATED PINS. THE MICROLOGIC WAS REMOVED AND OPENED. THE CHIP EXHIBITED A MOTTLED APPEARANCE WITH NUMEROUS ERUPTIONS IN THE METALLIZATION. CHEMICAL ANALYSIS INDICATED HIGH TIN AND CHLORIDE CONTENT IN THE AFFECTED AREAS.

# LEAK TEST FLOW DIAGRAM







DELCO ELECTRONICS

DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201

# DUAL NORGATE INTEGRATED CIRCUIT P/N 100 6321

## USAGE:

COMPUTER - 2,432 PARTS/COMPUTER  
 ECDU - 1,304 PARTS/ECDU  
 TOTAL - 159,344 PARTS

## OPERATING HOURS: (AS OF 1 NOV. 70)

COMPUTER - 128,200,448 PART HOURS  
 ECDU - 60,094,84 PART HOURS  
 TOTAL - 188,295,288 PART HOURS

## HISTORY:


FAILURES DUE TO LIFTED BONDS  
 BUILD CYCLE - 9  
 FIELDS - 3

## FIELD FAILURE SUMMARY

SEPT 1970, ECDU S/N 47, READ COUNTER S/N 269, LOT #<sup>99</sup>  
 SEPT 1970, ECDU S/N 48, READ COUNTER S/N 231, LOT 0521  
 JAN 1969, COMPUTER S/N 43, A-6 LOGIC MODULES S/N 44, LO  
 03311

## MOTOR TACHOMETER

LUBRICANT LOSS DURING LIFE OF OUA MOTOR-TACH




LIMITED LIFE ITEMS

PART NUMBER, DESCRIPTION	LOWEST REPLACE- ABLE ASSEMBLY	REPLACEMENT CRITERIA	TOTAL TEST TIME/CYCLES	RATIONALE
Motor-tachometer P/N 1012156-4  S/N 1258 S/N 1267 S/N 1268 S/N 1306	OUA-21	4 Years since lubrication	4.2 Years at completion of mission	<p><u>Condition</u></p> <ol style="list-style-type: none"> <li>1. Based upon the test data from 2-year and 3-year old motors, the lubrication quantity retained (LQR) in the bearings was extrapolated to 4 years (assuming that this period was adequate to certify the motor-tachs in Apollo 14) and found to be approximately 0.3 mg and considered flightworthy.</li> <li>2. Projected LQR curve is biased conservative since 3/4 of actual test motor-tachs LQR was above the curve used for the extrapolation in the above paragraph.</li> <li>3. The maximum dispersion between similar motor-tachs was 2.5 mg.</li> </ol> <p>Test Data from 3-year old motor-tachs was analyzed.</p> <ol style="list-style-type: none"> <li>1. All motor-tachs tested to determine flightworthiness as a function of time operated satisfactorily with little or no measurable lubricant. One motor-tach was run with completely dry bearings without anomaly.</li> <li>2. Lubricant depletion during normal operation at <math>\approx 0.6</math> mg/yr after the first year.</li> <li>3. Lubricant depletion during operation at KSC (including altitude test and operation) and during nominal lunar mission <math>\approx 0.2</math> mg.</li> <li>4. A supplementary 120-day test in vacuum to a simulated mission profile was performed without significant motor-tach lubricant depletion.</li> </ol> <p><u>Conclusion</u></p> <ol style="list-style-type: none"> <li>1. Recognizing the above conditions and test data it is evident that there is little difference between a 4-year-old motor-tach and one that is 4.2 years old.</li> <li>2. Based on the LQR curve projection there would be 0.2 mg of lubricant remaining before the Apollo 14 mission.</li> <li>3. Since <math>\approx 0.2</math> mg is exhausted during the mission and the motor-tachs tested performed nominally on zero and immeasurable lubricant, OUA-21 in Apollo 14 is considered flightworthy. There is an element of risk in the extrapolation; it is considered that this risk is acceptable.</li> </ol>


**DELCO ELECTRONICS**  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201




APOLLO 12/CSM 108 OPTICS CDU SHAFT ANGLE DATA



OPTICS SHAFT ANGLE LONG-TERM STABILITY



• OPTICS ZERO DRIFT



- Modes
- 1. Man
  - 2. CMC
  - 3. Zero Optics

# CM-109/CM-110 CONFIGURATION DIFFERENCES

- 1) MISSION PECULIAR ITEMS INCLUDE COMANCHE 108 FLIGHT ROPES, STAR LIST, ALIGNMENT PROCEDURE PANEL, CHECK LIST AND ALARM CODES, VERBS/NOUN LIST
- 2) CMC-45 INCLUDES A RESTART MONITOR MODULE, WHICH HAS NOT PREVIOUSLY FLOWN.
- 3) GNIC-13 INCLUDES THE COMPUTER AIDED OPTICS MODIFICATION, WHICH HAS NOT PREVIOUSLY FLOWN.
- 4) SXT MIRROR HOUSING INCLUDES A HALO LIGHT SHIELD WHICH HAS NOT PREVIOUSLY FLOWN.

REUSED HARDWARE

NONE

# QFN 214 READY SPARES SUPORT FOR APOLLO 14

---


1) ONLY THE FOLLOW EQUIPMENT IS AVAILABLE AT  
KSC.

<u>PART No</u>	<u>COMPONENT</u>	<u>S/N</u>
2007234-021	SCA	1
2010802-	FLIGHT ROPES	

OTHER SPARES ARE LOCATED AT DELCO, NAR  
AND GAC.


IMU/PTA	SN-29 AND 13
COMPUTER	52
ECDU	23
PSA	24

THE FOLLOWING PAGES SHOW WHATS IN  
THE SYSTEM AND HOW IT GOT THERE.





G & N 214 SYSTEM SUMMARY

EQUIPMENT	PART NUMBER	S/N	OPERATING HOURS AS OF 10-31-70	WEIGHT
Inertial Measurement Unit (IMU)	2018601-231	7	3003	41.1
IRIG X		8A109		
Y		8A107		
Z		8A111		
PIPA X		2AP97R		
Y		2AP150		
Z		2AP185		
Blower Motors	2018644	208	211	
		210	211	
PIPA Electronics Assembly (PEA)	2007201-031	5	3220	8.4
CM Guidance Computer (CMC)	2003993-111	45(C-29)	317	59.2
Flight Ropes	2010802-xxx	--*		12.4
DSKY Main	2003994-121	77 (D-44)	898	18.2
DSKY Navigation	2003994-121	69 (D-36)	895	18.1
Power and Servo Assembly (PSA)	2007200-151	10	2523	49.7
Signal Conditioner Assembly (SCA)	2007234-021	12	460	5.9
G & N Indicator Control Panel (GNIC)	2021290-051	13	514	14.6
Interconnect Harness Group	2014567-071	28		24.4
Navigation Base	2899982-031	16		11.2
Optical Unit and Bellows Assembly	2010790-181	7		60.4
Optical Unit Assembly (OUA)	2011000-081	21	735	--
Electronic Data Coupling Unit (ECDU)	2007222-181	23	1320	36.7
Optics Shroud	2021394-011	5		3.5
Eyepiece Storage Unit (ESU)	2021382-021	12		7.0
Astro sextant Passive Thermal Protective System Assembly (APTPS)	1021373-051	5		4.8
Dust Covers (External)	1021352/62	12, 12		--
(Internal)	2012796/97	8, 5		0.5
Verb Noun	2021472	TBA		--
Star Chart	2021473	TBA		--
Check List and Alarm Codes	2021474	TBA		--
Eyepieces				
SCT Eyepiece	2012793-011	2023		2.0
SCT Prism Assembly	2012775	2023		1.1
SXT Eyepiece	2012700-011	2016		0.7
SXT Mirror Assembly	2012791-021	2006		1.3
SCT Long Eye Relief	2012790-011	2022		1.7
SXT Long Eye Relief	2012748-011	2021		0.5
Installation Kits (CMC)	2004199-011	16		(in CMC wt)
(OUA)	2899950-021	15		4.5
IMU Coolant Hoses (2)	2018621-021	120, 129		1.0
<b>TOTAL</b>				<b>388.9</b>
* Flight Ropes — Comanche Rev. 108, Set 1				
P/N 2010802-181, S/N 424		P/N 2020802-221, S/N 427		
191, S/N 425		231, S/N 422		
211, S/N 426		241, S/N 423		



DELCO ELECTRONICS  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201







- CMC RESTART DR-11
- FINE ALIGN SWITCHING TRANSIENTS DR-5
- REDUCTR INCREMENTED DR-6


DELCO ELECTRONICS  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201








**DELCO ELECTRONICS**  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201



DELCO ELECTRONICS  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201


MODEL 15-0010 GEN/214 INSTALL



DELCO ELECTRONICS  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201

# CM-110, GEN 614, CMC S/N 45


VIB. TIME: YA-YB MODULE LEVEL 3 MIN.; YA-YB COMPUTER LEVEL 14 MIN.



DELCO ELECTRONICS  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201

X IRIG UNIT NO. 8A109


12/3/70  
~~09/09/70~~



LEGEND: ○ NBO ▲ ROSRA ◆ ROIA

# Y IRIG UNIT NO. 8A107


12/03/70  
09/09/70



LEGEND: ○ NDO ▲ ADSRA ◊ ADIA

Z IRIG UNIT NO. 8A111

12/3/70  
05/09/70




LEGEND: ○ NBO ▲ ADSRA ◊ ADIA

0023-31-11



X PIPA UNIT NO. 2AP97


~~09/09/70~~ 12/03/70



LEGEND: ○ SF ▲ GBIAS ◻ NBIAS

Y PIPA UNIT NO.2AP150

12/03/70  
~~09/09/70~~



LEGEND: ○ SF △ GBIAS ○ NBIAS

Z PIPA UNIT NO. 2AP185

~~09/09/70~~  
12/03/70



LEGEND: ○ SF ▲ GBias ○ NBias

# LM

## LM-GENERIC ITEMS

- 1) AN ADDED PREVENTIVE MAINTENANCE REQUIREMENT FOR IMU BLOWER MOTORS (2,000 HOURS) IS BEING APPLIED TO IMU'S RECYCLED FOR RETEST/REPAIR OR MODIFICATION. THE BLOWER MOTORS IN IMU 21 ARE WELL WITHIN THE PREVENTATIVE MAINTENANCE PERIOD, HAVING EXPERIENCED 1,725 HOURS (S/N 80) AND 765 HOURS (S/N 213).
- 2) IMU QUICK DISCONNECTS ARE TO BE REPLACED AFTER 20 HOURS EXPOSURE TO ISOPROPYL ALCOHOL. IMU QUICK DISCONNECT COUPLINGS WERE REPLACED IN IMU 21 AT THE FACTORY. THE INSTALLED QUICK DISCONNECT, P/N 1000135, S/N 51 HAS HAD 6.5 HOURS, AND S/N 432 HAS HAD ZERO HOURS EXPOSURE TO ISOPROPYL ALCOHOL SINCE REPLACEMENT.
- 4) DSK EL MODULES ARE BEING VACUUM TESTED IN ORDER TO DETECT POSSIBLE SAFETY GLASS DELAMINATIONS. THIS HAS BEEN IMPLEMENTED ON LM-8, DSKY S/N.
- 5) FLATPACK CONTAMINATION. LGC-49 HAS COMPLETED 112 MINUTES OF COMPUTER LEVEL YA-YB VIBRATION SCREENING. HOWEVER, NO MODULE-LEVEL FLATPACK VIBRATION SCREENING FOR CONTAMINATION HAS BEEN ACCOMPLISHED ON THIS UNIT. ECDU-28 MODULES ALSO HAVE NOT EXPERIENCED ANY MODULE-LEVEL YA-YB VIBRATION SCREENING.

- 6) RELAY VIBRATION SCREEN. THE DSKY RELAYS HAVE BEEN VIBRATED AT THE SYSTEM LEVEL FOR CONTAMINATION DETECTION. THE DSKY 96 IDM MODULES HAVE NOT COMPLETED THE VIBRATION SCREEN AT THE MODULE LEVEL.

## PROBLEM REVIEW

### ECDU-47

#### PROBLEM:

AN IMU CDU FAIL/ISS WARNING OCCURRED DURING VERTICAL DRIFF TEST WHILE Q&N 616 WAS BEING TESTED AT DELCO. WHEN THE INNER GIMBAL WAS COARSE ALIGNED TO AN ANGLE OF  $2.8^{\circ}$  OR GREATER, THE ECDU INNER GIMBAL AXIS BECAME UNSTABLE, WITH THE READ LOOP EITHER COUNTING CONTINUOUSLY OR BREAKING INTO A LIMIT CYCLE.

#### VERIFICATION:

ECDU S/N 47 WAS REMOVED FROM Q&N 616. ECDU S/N 47 WAS TESTED AT THE ECDU LEVEL. THE FAILURE WAS VERIFIED AS AN UNSTABLE INNER GIMBAL ECDU FINE READ LOOP. THE READ LOOP ERROR TEST INDICATED A LOOP INSTABILITY AT FINE RESOLVER ANGLE.

THE ECDU WAS THEN TESTED IN AN ENGINEERING LABORATORY SYSTEM. THE FAILURE OF INNER GIMBAL CONTINUOUS COUNTER OR LIMIT CYCLE PROBLEM REPEATED. THE IQ READ COUNTER AND THE IQ QUADRANT SELECTOR MODULES WERE SWAPPED AND THE PROBLEM FOLLOWED THE IQ READ COUNTER S/N 260 AND WAS ISOLATED TO GATE 6-605 ON ASSOCIATED LEADS.

### ISOLATION:

READ COUNTER P/N 2007140, S/N 269 WAS SENT TO RAYTHEON TO PERFORM ISOLATION TESTING, WHERE IT WAS DETERMINED THAT THE TOP LEAD OF GATE 6-605 WOULD NOT PRODUCE A LOGIC "ONE". THE MODULE WAS DEPOTTED AND THE FAILURE VERIFIED AT THE 6-605 GATE. RAYTHEON FAILURE ANALYSIS STATES:

- 1) THE ANALYSIS OF ELECTRICAL TESTS SHOWED AN OPEN AT PIN 1 OF GATE 6-605, AND AN ABNORMALLY HIGH RESISTANCE IN SERIES WITH THE EMITTER OF ABOUT 170 OHMS.
- 2) WHEN THE BONDING WIRES WERE PULL TESTED, THE DIE BALL BONDS ASSOCIATED WITH PINS 1, 5, AND 6 LIFTED AT ZERO GRAMS FORCE. THE VISUAL APPEARANCE OF THE BONDING REGIONS INDICATED THAT FORMATION OF GOLD ALUMINUM COMPOUNDS

(INTERMETALLIC COMPOUNDS) PLAYED A ROLE IN WEAKING THE BONDS, THE BONDS LISTED IN THE GOLD RICH REGION.

## ECDU - 48

### Problem:

READ COUNTER WAS STABLE AT  $11 \frac{1}{4}$  INCREMENTS WHILE THE ECDU TRUNNION LOOP BECAME UNSTABLE AT ALL OTHER ANGLES BREAKING INTO A CONTINUOUS UP COUNT CAUSING THE ECDU TRUNNION LOOP TO LIMIT CYCLE. PROBLEM OCCURRED IN G&N CONFIGURATION AND ACCEPTANCE TEST OF G&N 616 WHEN RENDEZVOUS RADAR POWER WAS APPLIED.

### VERIFICATION:

PROBLEM WAS DUPLICATED AND VERIFIED IN AN ISS TEST CONFIGURATION AND THE ENGINEERING LABORATORY SYSTEM. ISOLATION WAS COMPLETED TO THE READ COUNTER MODULE S/N 231 AND FINALLY VERIFIED BY SWAPPING MODULES. THE PROBLEM FOLLOWED READ COUNTER S/N 231.

### ISOLATION


THE READ COUNTER MODULE S/N 231 WAS SHIPPED TO RAYTHEON AND



TESTED IN PART AT THE MODULE LEVEL. THE  $2^{-10}$  COUNTER STAGE WAS VERIFIED TO BE INOPERATIVE. TESTING OF THE FINE LOGIC D9 OUTPUT SIGNAL APPEARED TO BE NORMAL (1.5V); HOWEVER, THE TESTING WAS NOT COMPLETE. THE MODULE WAS THEN TESTED ON THE MANUAL TEST FIXTURE AND THE FINE LOGIC ANOMALY REPEATED AND ISOLATED TO GATE 6-591. A STATIC INPUT TEST WAS PERFORMED TO ISOLATE THE  $2^{-10}$  COUNTER BIT PROBLEM. TESTING OF CIRCUITRY REVEALED GATE 6-501 WAS NOT FUNCTIONAL. GATE-501 IS THE SISTER GATE TO 591 WHICH HAD BEEN PREVIOUSLY DEFINED AS THE CAUSE OF THE FINE LOGIC PROBLEM. RAYTHEON FAILURE ANALYSIS REPORT STATED THAT THE FLATPACK FAILED DUE TO MULTIPLE OPENS ASSOCIATED WITH PINS 2, 5, 6, 7, 8 AND 10. THE OPENS WERE DUE TO LIFTED GOLD BONDS AT THE DIE. IT APPEARS THAT THE BOND FAILURES WERE RELATED TO THE FORMATION OF GOLD ALUMINUM INTERMETALLIC COMPOUNDS (THE BOND LIFTED IN THE GOLD RICH REGION).



TYPICAL GOLD ALUMINUM THERMOCOMPRESSION BOND

WITH PHASES IDENTIFIED





## ECD - 26

### Problem:

DURING LM-8, G4N 611 TESTING AT KSC AND AFTER A COARSE ALIGN COMMAND OF THE O<sub>9</sub> AXIS FROM 270° TO 0°, THE O<sub>9</sub> WAS IN ERROR BY APPROXIMATELY 194°. THE FINE ERROR AND DAC OUTPUT VARIED IN PHASE AND MAGNITUDE INDICATING LARGE ERRORS IN THE ECDU READ LOOP. THE O<sub>9</sub> 16X SINE OUTPUT INDICATED AN INTERMITTENT READ LOOP AND PERIODICALLY DROVE IN ONE DIRECTION AT 35°/S RATE.

### Verification:

ECDU-26 WAS REMOVED FROM G4N 611 AND RETURNED TO DELCO. IN ENGINEERING LABORATORY TESTS THE OUTER GIMBAL COARSE ALIGN PROBLEM WAS REPEATED AND VERIFIED. MSA AND QUAD REJECT MODULE S/N 127 FAILURE RESULTING IN THE LOSS OF FINE TERNARY OUTPUT WAS VERIFIED DURING A SINGLE AXIS ECDU CLOSED READ LOOP TESTING.

### Isolation:

MSA AND QUAD REJECT MODULE S/N 127 WAS SENT TO FAILURE ANALYSIS. THE FAILURE WAS CAUSED BY A HIGH RESISTANCE CONDITION BETWEEN TERMINAL NO. 2 AND NO. 3 OF TRANSFORMER T-1, P/N 1010274. THE FAILURE WAS ISOLATED TO AN OPEN CIRCUIT IN THE 2-3 SECTION OF THE PRIMARY WINDING. A FRACTURE AND KINK WERE FOUND AT THE FLANGE OF THE BOBBIN WHERE THE WINDING PROCESS REVERSES. APPARENTLY THE KINK, BEING TRAPPED BETWEEN THE BOBBIN FLANGE AND THE PRECEDING LAYER WIRE, WAS SUBJECTED TO COMPRESSION DURING THERMAL EXPANSIONS OF THE MODULE.

THE REPEATED COMPRESSIONS RESULTED IN THE FRACTURE.

### FINE WIRE TRANSFORMER FAILURE HISTORY



APPROXIMATELY 326 FINE WIRE TRANSFORMERS (AWG # 40 OR SMALLER) ARE USED PER APOLLO MISSION INCLUDING BOTH CM AND LM. THESE TRANSFORMERS ARE OF 24 DIFFERENT PART NUMBER TYPES. FOURTEEN (14) OF THE 24 TYPES HAVE NOT EXPERIENCED FAILURES OF ANY KIND THROUGHOUT THE LIFE OF THE PROGRAM. FIELD FAILURES HAVE BEEN EXPERIENCED ON 4 OF THESE 24 TYPES. THESE FAILURES, ALL OF WHICH INVOLVE OPEN WINDINGS, ARE DETAILED AS FOLLOWS:

<u>PART NUMBER</u>	<u>HISTORY</u>
1008842	1 FIELD FAILURE IN LM-10 AT GAC IN 1969
1010274	3 FIELD FAILURES (1) IN CM-2TV-1 AT NAR IN 1969 (1) IN THE NAR LABS. IN 1969 (1) IN CM-110 AT KSC IN 1969
1010324	1 FIELD FAILURE IN LM-1 AT KSC IN 1969
1010753	1 FIELD FAILURE IN MSC LAB. (PI-4) IN 1969

\* THIS FAILURE RESULTED FROM DAMAGE TO THE TRANSFORMER DURING A PREVIOUS REPAIR AND WAS NOT CAUSED BY THE PART ITSELF.

LM 8 FAILURE

TRANSFORMER, P/N 1010274 ECDU, S/N 26



# LM-6/LM-7 CONFIGURATION DIFFERENCES

## 1) MISSION PECULIAR ITEMS

FLIGHT ROPES IN LM 8 WILL BE LUMINARY 178 SET 1. LM-7 FLIGHT ROPES WERE LUM 131, REVISION 1, SET 1.

2) LM-8 LGC CONFIGURATION INCLUDES A RESTART MODULE NOT PREVIOUSLY FLOWN.

## REUSED HARDWARE

NONE

# G & N 611 READY SPARES SUPPORT FOR APOLLO 14


1) ONLY THE FOLLOWING EQUIPMENT IS AVAILABLE AT KSC.

<u>PART NO</u>	<u>COMPONENT</u>	<u>S/N</u>
6614512-081	CLRD	8, 7
6007013-021	SCA	6
2010802	FLIGHT ROPES	SET 2

OTHER SPARES ARE LOCATED AT DELCO, GAC AND KIC.

IMU/PTA	S/N 12 AND 5
PSA	15
ECDU	32
LGC	55
DSKY	68
AOT	25

THE FOLLOWING PAGES SHOW WHATS IN THE SYSTEM AND HOW IT GOT THERE




G & N 611 SYSTEM SUMMARY

EQUIPMENT	PART NUMBER	SERIAL NUMBER	OPERATING HOURS AS OF 31 OCT 70	WEIGHT (lb)
IMU Assembly (IMU)	2018601-221	21	2,759	41.0
PIP Assembly, Prealigned	2018844-021	X - 2 AP 222 Y - 2AP 92R Z - 2AP 228		
25 IRIG Assembly	2021500-111	X - 8C 124 Y - 8A 139 Z - 8A 122	1,054 673 1,109	
Blower Motors	2018644	80 213	1,725 765	
Pulse Torque Assembly (PTA)	6007000-041	10	2,354	14.5
Power and Servo Assembly (PSA)	6007200-081	6	2,402	17.8
Electronic Data Coupling Unit (ECDU)	2007222-261	28	1,075	37.5
Computer Control and Reticle Dimmer Assy	6014512-081	14	312	1.6
Signal Conditioner Assembly (SCA)	6007013-021	5	750	5.6
LM Guidance Computer (LGC)	2003993-071	49	1,457	58.3
DSKY	2003994-091	96	906	18.4
Alignment Optical Telescope (AOT)	6011000-111	21	86	23.8
Navigation Base Assembly	6899980-021	11		5.3
A Harness	6010677	23		15.8
B Harness	6010678	27		4.4
AOT Conical Sunshade and Radar Shield	6011876	6		—
High Density Filter Assembly	6022856	108		0.1
Installation Kit, Computer	6004000-051	31		0.4
Installation Kit, SCA	6007020	6		0.1
Flight Ropes	2010802-xxx	— <sup>1</sup>		12.4
			Total	257.0
<sup>1</sup> Flight Ropes — Luminary Revision 178				
	P/N 2010802-321	S/N 430	P/N 2010802-351	S/N 439
	-331	S/N 431	-361	S/N 434
	-341	S/N 432	-371	S/N 435


**DELCO ELECTRONICS**  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201




# LM8, GEN G11 IN-HOUSE SEQUENCE




**DELCO ELECTRONICS**  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201




DELCO ELECTRONICS  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201



DELCO ELECTRONICS  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201



**DELCO ELECTRONICS**  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201



S/C DR 399/WAIVER  
AC-KSC-37 AFR 19092

S/C DR 286  
AFR 19093

S/C DR 497 (USE AS IS)


WAIVER AC-KSC-39

AFR 6201 IDR #13

DR 835


S/CDR 159 AFR 6201

DELCO ELECTRONICS  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201



**DELCO ELECTRONICS**  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201


LM-8, GEN 611, IMU S/N 21



DELCO ELECTRONICS  
 DIVISION OF GENERAL MOTORS CORPORATION  
 MILWAUKEE, WISCONSIN 53201

LM-6 GEN 611, LCC 64140

VIB TIME: Y<sub>A</sub> Y<sub>B</sub> MODULE LEVEL 0; Y<sub>A</sub> COMPUTER LEVEL 57 MIN; Y<sub>B</sub> COMPUTER LEVEL 55.12 MIN



DELCO ELECTRONICS  
DIVISION OF GENERAL MOTORS CORPORATION  
MILWAUKEE, WISCONSIN 53201





Y IRIG UNIT NO. 8A139


12/03/70  
~~09/09/70~~




LEGEND: ○ NDD, △ ROSRA, □ RDIH

0023-30-7

Z IRIG UNIT NO. 8A122 12<sup>03</sup> 09/09/70




LEGEND: o NDD, ADSRA, COIA



LEGEND: ○ SF ▲ COIAS ◇ NBINS

Y PIPA UNIT NO. 2AP92

12/03/  
~~09/03/70~~




LEGEND: ○ SF ▲ CBIAS ◻ NBIAS

0023-30-15

Z PIPA UNIT NO. 2AP228

12/03/70  
~~09/09/70~~



LEGEND: ○ SF ▲ GBIAS □ NBIAS

0023-30-18