

P. 1-4

Name of Program(s): LUMINARYOriginator: DAVID H. MOOREOrganization: MIT/ILDate: June 13, 1969

Description of Change: Fix R13 for check if in P66 before check for mode control in AUTO. (Change is for LUM 1B. Program) [R13 is AUTO-MODES-MONITOR ROUTINE]

Reason: If change not in, placing DAP in AUTO the following will occur:

- 1) significant number of R.O.D. "clicks" disregarded.
- 2) Increase of computer execution time by 5%.

Assigned to:

Dave Moore

Comments:

Hamilton
Cherry
Rye
Schulenberg
Eyles
Conelli

Approved by:

Mayant Hamilton

Date:

June 13, 1969