



$$H_1(n) = \begin{bmatrix} h_{11}(n) & h_{12}(n) \end{bmatrix}^T$$

$$H_2(n) = \begin{bmatrix} h_{21}(n) & h_{22}(n) \end{bmatrix}^T$$

$$H_3(n) = \begin{bmatrix} h_{31}(n) & h_{32}(n) \end{bmatrix}^T$$

n	0	...	$n_{\delta,2} - 1$	$n_{\delta,2}$...	$n_{\delta,3} - 1$	$n_{\delta,3}$...	$N - 1$	N	...	$n_{\delta,2} + N - 1$	$n_{\delta,2} + N$...	$n_{\delta,3} + N - 1$	$n_{\delta,3} + N$...
$H_1(n)$	$H'_1(0)$...	$H'_1(0)$	$H'_1(0)$...	$H'_1(0)$	$H'_1(0)$...	$H'_1(0)$	$H'_1(1)$...	$H'_1(1)$	$H'_1(1)$...	$H'_1(1)$	$H'_1(1)$...
$H_2(n)$	$H'_2(0)$...	$H'_2(0)$	$H'_2(1)$...	$H'_2(1)$	$H'_2(1)$...	$H'_2(1)$	$H'_2(1)$...	$H'_2(1)$	$H'_2(2)$...	$H'_2(2)$	$H'_2(2)$...
$H_3(n)$	$H'_3(0)$...	$H'_3(0)$	$H'_3(0)$...	$H'_3(0)$	$H'_3(1)$...	$H'_3(1)$	$H'_3(1)$...	$H'_3(1)$	$H'_3(1)$...	$H'_3(1)$	$H'_3(2)$...