

Name of Program(s): LUMINARY  
Originator: Bruce McCoy  
Organization: MIT  
Date: 10/20/69

## Description of Change:

Change MARKRUPT coding to look for ROD inputs as a decision maker, rather than lack of MARK or MARK REJECT. One of the present prevents P66 entrance

## Reason:

If the micro switch is used MARK & MARK reject pushbuttons cause channel bits in C13 to be set, the astronaut cannot enter P66; ROD bits are ignored

## Assigned to:

F. Kirven

## Comments:

Approved by:

*Margaret Hamilton*

Date:

10/20/69