


Title		
32 x 32 sensor driver (email: subramanian.s88@gmail.com; subrasundaram.com)		
Size	Number	Revision
A3		
Date:	5/29/2019	Sheet of
File:	Sheet1.SchDoc	Drawn By: Subramanian Sundaram



Note: Charging resistors (R_c) are not shown in this schematic and are not included in the PCB layout. They are added separately to each pin of connector P3 (i.e., Nets RD1...RD32) on the back side of the PCB and connected to V_{ref} (i.e., Net v_ref).

Title 32 x 32 sensor driver (email: subramanian.s88@gmail.com; subrasundaram.com)		
Size A3	Number	Revision
Date 5/29/2019	Sheet of	
File Sheet2.SchDoc	Drawn By: Subramanian Sundaram	